

## EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S1	648	(219/125.1). CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/01/26 10:13
S2	215	(219/137.9). CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/01/26 10:14
S3	476	(901/42).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/01/26 10:15
S4	128219	("219").CLAS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/01/26 10:16
S5	8576	("901").CLAS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/01/26 10:16
S6	136369	S4 or S5	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/01/26 10:16
S7	1	S6 and ((weld\$3 near5 robot) near50 ((power or voltage or current) near5 cable\$1) near50 (sensor or sensing or feedback))	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/01/26 10:18
S8	3	S6 and ((weld\$3 near10 robot) near100 ((power or voltage or current) near20 cable\$1) near100 (sensor or sensing or feedback))	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/01/26 10:18

S9	6	((weld\$3 near10 robot) near100 ((power or voltage or current) near20 cable\$1) near100 (sensor or sensing or feedback))	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/01/26 10:19
S10	6	((weld\$3 or torch) near10 robot) near100 ((power or voltage or current) near20 cable\$1) near100 (sensor or sensing or feedback))	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/01/26 10:20
S11	26	((weld\$3 or torch) near10 robot) near100 ((power or voltage or current) near20 (cable\$1 or line \$1)) near100 (sensor or sensing or feedback))	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/01/26 10:20
S12	1	((weld\$3 or torch) near10 robot) near100 ((power or voltage or current) near20 (cable\$1 or line \$1)) near100 (sensor or sensing or feedback)).clm.	US-PGPUB; USPAT	OR	OFF	2008/01/26 10:33

1/30/08 7:33:12 AM

C:\Documents and Settings\kkerns\My Documents\EAST\Workspaces\10566832(219)  
af.w.sp